## CCR Impoundment Weekly Inspection 35 III. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid		Date:	08/04/21
Impoundment Name:	Ash Pond		Time:	1:03 PM
IEPA Number:	W0218140002-03	1	Inspector(s):	1). Husar
Sky: P. Clausy Temp.:	·81°	Precip. (last 48 hrs):	0.0"	Pool Elev.: -18"
Sill	size denth extents.co	olor) and location in "DESCF	RIPTION" section. "NO" res	ponse indicates no issues were observe

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

					ACTION		
ITEM		ИО	DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM
CREST General Con	dition	Good	Fair / Poor Repairs:	Date:	_		
Cracking		V					-
Settlement		V			_		-
Erosion Rills		V			-		-
Animal Burrows		V					
Misalignment		V					-
Vegetation (greater than 12")		V		F 1			1
UPSTREAM EMBANKMENT General Con	ditior	Good	/ Fair / Poor Repairs:	Date:			
Cracking		V					
Sloughing / Bulging		V					-
Seepage		V			_		-
Sink Holes		V			_		+
Animal Burrows		/	1		_	<u> </u>	-
Erosion Rills		1		11.42			-
Slope Protection / Rip Rap		V			_	-	·
Vegetation (greater than 12")		V		Deter			
DOWNSTREAM EMBANKMENT General Cor	ndition:	Good	/ Fair / Poor Repairs:	Date:			
Cracking		V			-	-	
Sloughing / Bulging		V			_		+
Seepage		V				-	-
Sink Holes		V				+-	+
Sand Boils (indicate if flowing and color)		V		<b>Q</b>	V	-	-
Animal Burrows	V		FINDING + FILLIN			+-	+
Erosion Rills		1					
Vegetation (greater than 12")		IV		Date:	_	-	
	ndition	-	/ Fair / Poor Repairs:	Date.		-	-
Actively Flowing (provide depth)		V					-
Obstructions Present		V				+	+
Seepage					_		1
Sand Boils (indicate if flowing and color)		1					+
Erosion Rills		1					