CCR Impoundment Weekly Inspection 35 III ADM. Code 845 / 40 CFR Part 257

	35 ILL	. AUNI. COUE 643 / 40		08/18/21
Station:	Kincaid		Date:	
Impoundment Name:	Ash Pond		· Time:	1821
IEPA Number:	and the second s)1	Inspector(s):	1). Huber
Sky: Sway Temp.:	87°	Precip. (last 48 hrs):	0.00"	Pool Elev.: _ 15 "
YES" responses require description (t the time of inspection. If "ACTION dditional sheets as necessary. Circle	I" selected is "INVESTI	GATE", please indicate date	RIPTION" section. "NO" res forwarded via email to Dar	ponse indicates no issues were observed n Safety Manager (DSM) . Attach

ACTION NVESTIGATE MONITOR SENT TO DSM **DESCRIPTION** YES NO ITEM Date: General Condition Good /Fair / Poor Repairs: CILLOR Cracking Settlement **Erosion Rills** Animal Burrows Misalignment Vegetation (greater than 12") Date: UPSTREAM EMBANKMENT General Condition Good / Fair / Poor Repairs: Cracking Sloughing / Bulging Seepage Sink Holes **Animal Burrows Erosion Rills** Slope Protection / Rip Rap Vegetation (greater than 12") Date: DOWNSTREAM EMBANKMENT General Condition Good / Fair / Poor Repairs: Cracking Sloughing / Bulging V Seepage Sink Holes Sand Boils (indicate if flowing and color) FINDING + FILLING **Animal Burrows Erosion Rills** Vegetation (greater than 12") Date: Repairs: General Condition: Good / Fair / Poor SPILLWAY(S) Actively Flowing (provide depth) V **Obstructions Present** Seepage Sand Boils (Indicate if flowing and color) **Erosion Rills**