CCR Impoundment Weekly Inspection

Station:	Kincaid		Date:		·
Impoundment Name:	Ash Pond		Time:	6:30 PM	
IEPA Number:			Inspector(s):	1. Hubur	
r: CLEAN Temp.:	77015	Precip. (last 48 hrs):	1.49"	Pool Elev.:	-15'
responses require description (* 8		Power	re o

additional sheets as necessary. Circle General Condition for each section.

dditional sheets as necessary. Circle General Con						ACTION		
ITEM	YES P	NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO
CREST General Cond	dition (G	ood) Fair	r/Poor	Repairs:	Date:			
Cracking		V				_		-
Settlement		V				_		-
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V					-	-
Vegetation (greater than 12")	h	V			8.1		-	-
UPSTREAM EMBANKMENT General Con-	dition: (G		r / Poor	Repairs:	Date:			
Cracking		V					-	-
Sloughing / Bulging		V				_		-
Seepage		V					+	+-
Sink Holes		V					-	+
Animal Burrows		V					-	
Erosion Rills								_
Slope Protection / Rip Rap		V						+ -
Vegetation (greater than 12")		2			Dates			+
DOWNSTREAM EMBANKMENT General Con	dition:	ood/ Fa	ir / Poor	Repairs:	Date:			
Cracking		V					-	-
Sloughing / Bulging		V				_	-	+
Seepage		V					+	
Sink Holes		V					-	-
Sand Boils (indicate if flowing and color)		V		0 5 3 1 1 0		V	4	
Animal Burrows	V		ringing	& FILLING			-	+
Erosion Rills		V					-	
Vegetation (greater than 12")		V			Deta		-	-
SPILLWAY(S) General Cor	ndition:	Good Fa	air / Poor	Repairs:	Date:			-
Actively Flowing (provide depth)		V					-	-
Obstructions Present		V					+-	+
Seepage		V					+	+
Sand Boils (indicate if flowing and color)		V					-	-
Erosion Rills		V						