CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid	8	Date:	09/15/21
Impoundment Name:	Ash Pond		Time:	19:57
IEPA Number:	W0218140002-0	1	Inspector(s):	1). Huben
Sky: CLEAR Temp.:	85° F	Precip. (last 48 hrs):	0.00"	Pool Elev.: - 17 "
	(ciza danth avtents co	olor) and location in "DESCR	IPTION" section. "NO" resp	onse indicates no issues were observed

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

idditional sheets as necessary. Circle General Con		101 6	cn section.		ACTION		
		NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Con-	dition(Good	Fair / Poor Repairs: Date:				
Cracking		V				-	
Settlement		0				-	
Erosion Rills		V				-	
Animal Burrows		V				ļ .	
Misalignment		/				-	
Vegetation (greater than 12")			REGUEST MOWING	V		-	
UPSTREAM EMBANKMENT General Con	dition:	Good	Fair / Poor Repairs: Date:			-	
Cracking		2				-	
Sloughing / Bulging		V					
Seepage		V				-	
Sink Holes		V				-	
Animal Burrows		V	٠,			-	
Erosion Rills		V				-	
Slope Protection / Rip Rap		V	And the second	V			
Vegetation (greater than 12")			SZEGUEST MOWING	<u> </u>		+	
DOWNSTREAM EMBANKMENT General Cor	dition	: G000	/ Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V			-	-	
Sink Holes		V			ļ	-	
Sand Boils (indicate if flowing and color)		V	A Provide	V		-	
Animal Burrows			REquest Howing	<u> </u>	-	-	
Erosion Rills	1	V	a	_/	-		
Vegetation (greater than 12")			16Egues T Mowang	V	-	_	
	ndition	: doo	Fair / Poor Repairs: Date:		-		
Actively Flowing (provide depth)		IV			-		
Obstructions Present		V			-	-	
Seepage		V			-	+-	
Sand Boils (indicate if flowing and color)		V			-	-	
Erosion Rills		V					