CCR Impoundment Weekly Inspection

35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Kincaid Impoundment Name: Ash Pond

IEPA Number: W0218140002-01

Time:

Inspector(s): 1)

Sky: CLEAR

Temp.:

Precip. (last 48 hrs):

0.00

Pool Elev.:

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION	ACTION		
	YES			MONITOR	INVESTIGATE	SENT TO DSM
CREST General Con	dition	Good	Fair / Poor Repairs: Date:	Turn of the program	a secondary Sept.	
Cracking		V				\$17,000 m
Settlement	100000	V				
Erosion Rills		V				
Animal Burrows		V				
Misalignment		~				
Vegetation (greater than 12")		V		1		
UPSTREAM EMBANKMENT General Con	dition	Good	Fair / Poor Repairs: Date:			Milvii.
Cracking	eterroreier <i>mi</i>	V			a de la companya de l	eriore erriore una
Sloughing / Bulging	1	√			· · · · · · · · · · · · · · · · · · ·	
Seepage		V			İ	
Sink Holes		V				
Animal Burrows		✓	ı			
Erosion Rills		√				
Slope Protection / Rip Rap			·			
Vegetation (greater than 12")		V				
DOWNSTREAM EMBANKMENT General Con	dition:	Good	Fair / Poor Repairs: Date:		VIVE AND VI	n HASTATION Detworker
Cracking		V				
Sloughing / Bulging		V				
Seepage		V				
Sink Holes		V				
Sand Boils (indicate if flowing and color)		V	·			
Animal Burrows	V		Finding + FILLING	V		
Erosion Rills		V		- 1		
Vegetation (greater than 12")		V				
SPILLWAY(S) General Con	dition (Good	Fair / Poor Repairs: Date:			
Actively Flowing (provide depth)		V	and the second s			
Obstructions Present		7				
Seepage		V				$\vdash \dashv$
Sand Boils (indicate if flowing and color)	1	1				
Erosion Rills	1	V				