CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	35	LL. A	DM. Code 845 / 40 CFR Part 257	/ :			
Station: K			Date: ////フ /	21			
Impoundment Name: As			Time: 1 PM		70		
IEPA Number: W0218140002-0		2-01	Inspector(s): 1) Hwyw				
Sky: CLOUBY Temp.: 55	K	. F	· · · · · · · · · · · · · · · · · · ·	l Elev.:		5 ¹¹	
YES" responses require description (size, depth t the time of inspection. If "ACTION" selected dditional sheets as necessary. Circle General (is "INVES	TIGAT	r) and location in "DESCRIPTION" section. "NO" response indicates no "E", please indicate date forwarded via email to Dam Safety Manager ach section.	issues (DSM) .	were o	bserved	
					ACTION		
ITEM	YES	NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Co	ondition(Good	Fair / Poor Repairs: Date:				
Cracking		V					
Settlement		N	Value of the second of the sec				
Erosion Rills		V	,			<u> </u>	
Animal Burrows		V	\$1.5a				
Misalignment							
Vegetation (greater than 12")		V			, , , , , , , , , , , , , , , , , , ,		
UPSTREAM EMBANKMENT General Co	ondition:	Good	Fair / Poor Repairs: Date:	obstales	ing in		
Cracking		V		***************************************		DESCRIPTION OF THE PROPERTY OF	
Sloughing / Bulging		V		<u> </u>			
Seepage		V					
Sink Holes		V					
Animal Burrows		V		-			
Erosion Rills		V	,	\vdash			
Slope Protection / Rip Rap		V					
Vegetation (greater than 12")		V					
OWNSTREAM EMBANKMENT General Co	ndition:	ood	Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		7					
Sand Boils (indicate if flowing and color)		1/					
Animal Burrows	V		Finning / Freeing	V			
Erosion Rills		V					
Vegetation (greater than 12")		V					
SPILLWAY(S) General Co	ndition:/(ood /	Fair / Poor Repairs: Date:			4.50	
Actively Flowing (provide depth)	-	V		agi ji Mari Naga	n, italianga		
Obstructions Present	1 1	V					
Seepage	1	1/					
Sand Boils (indicate if flowing and color)	1 1	V					

Erosion Rills