## CCR Impoundment Weekly Inspection

35 ILL. ADM. Code 845 / 40 CFR Part 257

Date: 11   2 4   2 /
Time: 10 AM
Inspector(s): T. ARNOLD

Sky: PCLOUDY Temp.: SIF Precip. (last 48 hrs): 0.00" Pool Elev.: -14

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		1			ACTIO	N
	YES	NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM
CREST General Cor	nditioղ:	Good	/ Fair / Poor Repairs: Date:			
Cracking		V		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Settlement		V				
Erosion Rills		V				
Animal Burrows		J				
Misalignment		V				
Vegetation (greater than 12")		V				
UPSTREAM EMBANKMENT   General Cor	ndition	Good	/ Fair / Poor Repairs: Date:			
Cracking		V			7	eren Historiania (New Indiana)
Sloughing / Bulging		V				
Seepage		8,000				
Sink Holes		<b>V</b>				
Animal Burrows		V	1			
Erosion Rills		V		·		
Slope Protection / Rip Rap		V				
Vegetation (greater than 12")		V				
DOWNSTREAM EMBANKMENT General Con	dition:	Good	/ Fair / Poor Repairs: Date:			
Cracking		V		en I franzo est baraño III		
Sloughing / Bulging		V				
Seepage		2/				
Sink Holes		V				
Sand Boils (indicate if flowing and color)		<b>V</b>				
Animal Burrows			Finsing / Fillings	/		
Erosion Rills		/				
Vegetation (greater than 12")		V				
SPILLWAY(S) General Con	dition(	Good	/ Fair / Poor Repairs: Date:			anain.
Actively Flowing (provide depth)		V				
Obstructions Present		V				
Seepage		V				
Sand Boils (indicate if flowing and color)		V				
Erosion Rills		V				