CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

		17-5-00-1 -0 -			21 - 12 1	
Station:		Kincaid		Date:	12/18/11	
Impoundment Name:		Ash Pond		Time:	9:45 AM	
IEPA Number:		W0218140002-01		Inspector(s): D. Huben		
Sky: CLOUDY	Temp.:	61°F	Precip. (last 48 hrs):	0.03"	Pool Elev.:	-14"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ACTION NVESTIGATE **ITEM** YES NO DESCRIPTION MONITOR SENT TO DSM CREST General Condition: Good / Fair / Poor Repairs: Date: Cracking Settlement **Erosion Rills Animal Burrows** V Misalignment Vegetation (greater than 12") UPSTREAM EMBANKMENT | General Condition: Good | Fair / Poor Repairs: Date: Cracking Sloughing / Bulging Seepage Sink Holes V **Animal Burrows Erosion Rills** Slope Protection / Rip Rap Vegetation (greater than 12") DOWNSTREAM EMBANKMENT General Condition, Good Fair / Poor Repairs: Date: Cracking V Sloughing / Bulging V Seepage Sink Holes Sand Boils (indicate if flowing and color) FINDING **Animal Burrows Erosion Rills** Vegetation (greater than 12") SPILLWAY(S) General Condition: Good / Fair / Poor Repairs: Date: Actively Flowing (provide depth) **Obstructions Present** V Seepage Sand Boils (indicate if flowing and color) **Erosion Rills**