CCR Impoundment Weekly Inspection 35 III. ADM. Code 845 / 40 CFR Part 257

	35 ILL.	. ADIVI. Code 845 / 40	CFR Part 257	1 100
Station:	Kincaid		Date:	02/09/22
Impoundment Name:	Ash Pond		Time:	1330
IEPA Number:	W0218140002-0	1	Inspector(s):). Huben
Sky: Crousy Temp.:	42°F	Precip. (last 48 hrs):	0.00"	Pool Elev.: 17
YES" responses require description (at the time of inspection. If "ACTION additional sheets as necessary. Circle	" selected is "INVESTIG	GATE", please indicate date	RIPTION" section. "NO" respor forwarded via email to Dam Sa	nse indicates no issues were observed afety Manager (DSM) . Attach
				ACTION

ITEM			DESCRIPTION		ACTION			
		NO			MONITOR	INVESTIGATE	SENT TO DSM	
CREST Ge	neral Condition	Good	Fair / Poor Repairs:	Date:				
Cracking		V		-3				
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT Ge	neral Condition;	Good	Fair / Poor Repairs:	Date:				
Cracking		V						
Sloughing / Bulging		V						
Seepage		V	ă ă					
Sink Holes		V						
Animal Burrows		1	a 6					
Erosion Rills		V						
Slope Protection / Rip Rap		/						
Vegetation (greater than 12")		~						
DOWNSTREAM EMBANKMENT Ge	neral Condition;	Good	Fair / Poor Repairs:	Date:		Lagran		
Cracking		V	· · · · · · · · · · · · · · · · · · ·					
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V		_				
Sand Boils (indicate if flowing and color)		V						
Animal Burrows			Finding & FILLING	**************************************	V			
Erosion Rills		1	0			10		
Vegetation (greater than 12")		V						
	neral Condition:	Good	/ Fair / Poor Repairs:	Date:	a L			
Actively Flowing (provide depth)		V	*					
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		V						