CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	55 ILL. A	DIVI. CODE 843 / 40	CFR Fait 237	1 100	
Station:	Kincaid		Date:	02/16/22	i
Impoundment Name:	Ash Pond		Time:	1 PM	
IEPA Number:	W0218140002-01	1	Inspector(s):	D. Huber	
Sky: P. CLSY Temp.:	55°F P	recip. (last 48 hrs):	0.00	Pool Elev.:	-18"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO			ACTION			
			DESCRIPTION			INVESTIGATE	SENT TO DSM	
CREST General Con	ndition	Good	Fair / Poor Repairs: Date:					
Cracking		V						
Settlement		1						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT General Con	ndition	Good	Fair / Poor Repairs: Date:					
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Animal Burrows		V	331					
Erosion Rills		V						
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")		V						
DOWNSTREAM EMBANKMENT General Con	ndition:	Good	Fair / Poor Repairs: Date:	- 5-				
Cracking		V						
Sloughing / Bulging		V						
Seepage		V	•					
Sink Holes		V						
Sand Boils (indicate if flowing and color)		V						
Animal Burrows	/							
Erosion Rills		/						
Vegetation (greater than 12")		V	v *					
SPILLWAY(S) General Cor	ndition:	Good	Fair / Poor Repairs: Date:					
Actively Flowing (provide depth)		V						
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		V						