CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid		Date:	02/23/22	
Impoundment Name:	Ash Pond		Time:	1:00 PM	
IEPA Number:	W0218140002-0	1	Inspector(s):	1). Huban	
Sky: CLOUSY Temp.:	1901	Precip. (last 48 hrs):	0.09"	Pool Elev.:	-12"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION		
					MONITOR	INVESTIGATE	SENT TO DSM
CREST Gene	ral Condition:	Good	Fair / Poor Repairs:	Date:			
Cracking		V					
Settlement		V					
Erosion Rills		V					
Animal Burrows		V					
Misalignment		V	i i				
Vegetation (greater than 12")		IV					
UPSTREAM EMBANKMENT Gene	ral Condition:	Good	/ Fair / Poor Repairs:	Date:	25 10 5	1000	
Cracking		V					<u> </u>
Sloughing / Bulging		V					
Seepage		V			-		-
Sink Holes		V	1 1				
Animal Burrows		V	**				
Erosion Rills		V					
Slope Protection / Rip Rap		V					_
Vegetation (greater than 12")		V					
DOWNSTREAM EMBANKMENT Gene	eral Condition:	Good	/ Fair / Poor Repairs:	Date:		13.5	
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V				_	
Sand Boils (indicate if flowing and color)		~					
Animal Burrows			Finding / till	ng	V	_	-
Erosion Rills		V	0	0			
Vegetation (greater than 12")		V	* **				
	eral Condition	Goog	/ Fair / Poor Repairs:	Date:			
Actively Flowing (provide depth)		V					
Obstructions Present		V					-
Seepage		V					_
Sand Boils (indicate if flowing and color)		V					
Erosion Rills		V					11