CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:

Date: 03/16/22

Impoundment Name	: Ash Pond		Time:	1:30 PM	
IEPA Number	W0218140002-0	01	Inspector(s): D. Huba		
Sky: CLEAR Temp.	70°F	Precip. (last 48 hrs):	0.00"	Pool Elev.: -9 ')	

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM					ACTION		
		ES NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM	
CREST Ge	eneral Conditio	n. Good	Fair / Poor Repairs: Date:				
Cracking		1					
Settlement		V					
Erosion Rills		V					
Animal Burrows		V					
Misalignment		~					
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT Ge	neral Conditio	n: Good	Fair / Poor Repairs: Date:				
Cracking		V			(4)		
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Animal Burrows		V	0.11				
Erosion Rills		V					
Slope Protection / Rip Rap		V					
Vegetation (greater than 12")		V					
DOWNSTREAM EMBANKMENT Ge	neral Conditio	n: Good	Fair / Poor Repairs: Date:	YAR I	Tig.		
Cracking		W					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and color)		V					
Animal Burrows			Finoring / FILLING	V			
Erosion Rills		V.	0				
Vegetation (greater than 12")		1					
	neral Conditio	n. Good	/ Fair / Poor Repairs: Date:	= =,=			
Actively Flowing (provide depth)		V	-				
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)		V					
Erosion Rills		V					