## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid	_	Date:	04/20/22	
Impoundment Name:	Ash Pond		Time:	2:00 PM	
IEPA Number:	W0218140002-01		Inspector(s):	1). Huben	
Sky: Chows Temp.:	54° F	Precip. (last 48 hrs):	0.20"	Pool Elev.:	-11"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM			DESCRIPTION		-	ACTION		
		NO			MONITOR	INVESTIGATE	SENT TO DSM	
<b>CREST</b> Gen	eral Condition	Good	Fair / Poor Repairs:	Date:				
Cracking		18						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		1						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT Gen	eral Condition	Good	/Fair / Poor Repairs:	Date:				
Cracking		V						
Sloughing / Bulging		V						
Seepage		1						
Sink Holes		V						
Animal Burrows		V	a U					
Erosion Rills		V						
Slope Protection / Rip Rap		V	2					
Vegetation (greater than 12")		V						
DOWNSTREAM EMBANKMENT Gen	eral Condition:	Good	Fair / Poor Repairs:	Date:		(Sulfa	17	
Cracking		V						
Sloughing / Bulging		V	1				ď	
Seepage		V						
Sink Holes		/						
Sand Boils (indicate if flowing and o	color)	V			1 7			
Animal Burrows			Finory Przing		V			
Erosion Rills		V	0					
Vegetation (greater than 12")		V						
	eral Condition	Good	/ Fair / Poor Repairs:	Date:				
Actively Flowing (provide depth)		V						
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		V						