CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid	Date: 04/27/22	
Impoundment Name:	Ash Pond	Time: 11:00 AM	
IEPA Number:	W0218140002-01	Inspector(s): D. Huber	4)
Sky: LLEAR Temp.:	68°F	recip. (last 48 hrs): 0.00" Pool Elev.:	.0"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM			DESCRIPTION		1	ACTION		
		NO			MONITOR	INVESTIGATE	SENT TO DSM	
CREST G	eneral Condition	Good	Fair / Poor Repairs	: Date:				
Cracking		7		(8)				
Settlement		V					_	
Erosion Rills		1						
Animal Burrows		/						
Misalignment		/						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT G	eneral Condition	Good	/ Fair / Poor Repairs	: Date:				
Cracking		V						
Sloughing / Bulging		V					<u> </u>	
Seepage		V			_		_	
Sink Holes		1						
Animal Burrows		V	- 10					
Erosion Rills		V						
Slope Protection / Rip Rap		/						
Vegetation (greater than 12")		V						
DOWNSTREAM EMBANKMENT G	eneral Condition	Good	/ Fair / Poor Repairs	: Date:	KE L	The state		
Cracking		7						
Sloughing / Bulging		V						
Seepage		V,						
Sink Holes		V						
Sand Boils (indicate if flowing and color)		V						
Animal Burrows			Fraging 1 Fize	ing	V			
Erosion Rills		V	0	0				
Vegetation (greater than 12")		V	an d					
	eneral Condition	Good	/ Fair / Poor Repairs	: Date:				
Actively Flowing (provide depth		V						
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		V						