CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	35	ILL. A	DM. Code 845 / 4	0 CFR Part 257	,	10	2			
Station: Kind					Date: 05/0 Time: 12:3 ctor(s): 10	5412	L			
Impoundment Name: Ash P			ı		Time: 12:3	30 PM)			
IEPA Number: W021814		anna anna da indicator (Core	1	Inspec	ctor(s):	Hun	m.	ı		
	The second secon		1				ALL AND DESCRIPTION OF THE PERSON OF THE PER	_	11	
Sky: Crousy Temp.	:_ 56° F	p	recip. (last 48 hrs):	0.47		Pool El	lev.:	·l	6	
YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach dditional sheets as necessary. Circle General Condition for each section.										
						_	ACTION			
ITEM		s NO		DESCRIPTION	N		MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Condition	n/Good	/Fair / Poor	Repairs:	Date:					
Cracking	Statement and analysis and an experience of the statement	1						province and the same of		
Settlement		1								
Erosion Rills		V								
Animal Burrows		V			2/01-11-11-11-11-11-11-11-11-11-11-11-11-1					
Misalignment		V	MAN AND AND AND AND AND AND AND AND AND A					0.000	w/2000	
Vegetation (greater than 12")	1	Almania							
UPSTREAM EMBANKMENT	General Condition	n Good	Fair / Poor	Repairs:	Date:					
Cracking		V		O						
Sloughing / Bulging				ONTHE CONTROL OF THE				472000000000000000000000000000000000000		
Seepage		\ \ \								
Sink Holes		1								
Animal Burrows		V		1						
Erosion Rills		V								
Slope Protection / Rip Rap		1							L	
Vegetation (greater than 12"		1/								
OOWNSTREAM EMBANKMENT	General Condition	n (Good	/ Fair / Poor	Repairs:	Date:	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	- Company (August 1997)			
Cracking		V								
Sloughing / Bulging		V			DO					
Seepage		V		WARRANT TO THE PROPERTY OF THE PARTY OF THE						
Sink Holes		V								
Sand Boils (indicate if flowing and color)		V		<u> </u>						
Animal Burrows			Firming/	rrung			<u>v</u>			
Erosion Rills		<u>V</u>		V	A Committee of the Comm					
Vegetation (greater than 12")		1/								
SPILLWAY(S)	General Condition	<u> </u>	/JFair / Poor	Repairs:	Date:					
Actively Flowing (provide depth)		V			W. C.					
Obstructions Present		\ <u>'</u>								
Seepage		V		,						
Sand Boils (indicate if flowing and color)		V								

Erosion Rills