## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

35 ILL. ADIVI. Code 845 / 40 CFR Part 25/										
Station	: Kincaid		Date:	05/11/22						
Impoundment Name	: Ash Pond	ma .	Time:	11:30 AM						
IEPA Number	W0218140002-01		Inspector(s):	D. Huban						
Sky: CLSAN Temp.	90°F	Precip. (last 48 hrs):	0.00"	Pool Elev.:	-14"					

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION		
					INVESTIGATE	SENT TO DSM	
CREST General C	ondition.	Good	/ Fair / Poor Repairs: Date:	4		JI 35	
Cracking		V		¥			
Settlement		V					
Erosion Rills		V					
Animal Burrows		V					
Misalignment		1					
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT General C	ondition;	Good	Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		<b>V</b>					
Seepage		V					
Sink Holes		V					
Animal Burrows		V	5				
Erosion Rills		V					
Slope Protection / Rip Rap		V				-	
Vegetation (greater than 12")		X					
DOWNSTREAM EMBANKMENT General C	ondition:	Good	Fair / Poor Repairs: Date:		1 135		
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and color)		V			_		
Animal Burrows	V		FINDING/ FILLING	V			
Erosion Rills		V	0				
Vegetation (greater than 12")		V					
SPILLWAY(S) General Co	ondition(	Good	Fair / Poor Repairs: Date:			,	
Actively Flowing (provide depth)		V					
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)		V					
Erosion Rills		V					