## **CCR Impoundment Weekly Inspection**

	35 ILL. /	ADM. Code 845 / 40	CFR Part 257	1 2 1 2 2
Station:	Kincaid		Date:	05/18/62
Impoundment Name:	Ash Pond		Time:	1:38 PM
IEPA Number:	W0218140002-01	-	Inspector(s):	D. Hubun
Sky: <u>CLEAR</u> Temp.:	77°F	Precip. (last 48 hrs):	0.53"	Pool Elev.: -16 "
YES" responses require description ( at the time of inspection. If "ACTION	size, depth, extents, colo " selected is "INVESTIGA	TE", please indicate date	RIPTION" section. "NO" res forwarded via email to Dan	ponse indicates no issues were observed n Safety Manager (DSM) . Attach

additional sheets as necessary. Circle General Condition for each section. ACTION

ITEM		NO	DESCRIPTION		ACTION		
					MONITOR	INVESTIGATE	SENT TO DSM
CREST Genera	l Condition	Good	/Fair / Poor Repairs:	Date:			
Cracking		V		4			
Settlement		V					
Erosion Rills		V					
Animal Burrows		V					
Misalignment		/					
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT Genera	I Condition.	Good	Fair / Poor Repairs:	Date:			
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Animal Burrows		V	3				
Erosion Rills		V		=			
Slope Protection / Rip Rap		V					
Vegetation (greater than 12")		V	_				
DOWNSTREAM EMBANKMENT General	l Condition:	Good	/ Fair / Poor Repairs:	Date:	1	Te-dia	- /-
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and colo	or)	V					
Animal Burrows	V		Finding / Fireling	7	V		
Erosion Rills		V		/			
Vegetation (greater than 12")		V					
SPILLWAY(S) Genera	l Condition.	Good	Fair / Poor Repairs:	Date:	,		
Actively Flowing (provide depth)		7					
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)							
Erosion Rills		V					