## CCR Impoundment Weekly Inspection 35 III ADM, Code 845 / 40 CFR Part 257

		55 ILL.	ADIVI. Code 645 / 44	, GITT OIL III.	41. 122		
Station: _ Impoundment Name:		Kincaid	Date: 06/01/22				
		Ash Pond	<del></del> -	Time: 1:38 PM			
IEPA Num			1	Inspector(s)	D. Hubur		
Sky: RaiN Te	mp.:	76° F	Precip. (last 48 hrs):	0.60"	Pool Elev.: -14.0		

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		1	T	DESCRIPTION			ACTION			
		ES N	10				MONITOR	INVESTIGATE	SENT TO DSM	
CREST	Seneral Conditio	n/Go	od	Fair / Poor	Repairs:	Date:				
Cracking			7			× .	-		-	
Settlement			/						-	
Erosion Rills		1	1				-			
Animal Burrows		V	/						-	
Misalignment		١	/_				-			
Vegetation (greater than 12")		V					-		-	
UPSTREAM EMBANKMENT	General Condition	n: Go	od	Fair / Poor	Repairs:	Date:			-	
Cracking			V							
Sloughing / Bulging		,	V						-	
Seepage		ν	/					-	-	
Sink Holes		ν	/,				-	-	-	
Animal Burrows		١	/		i .		-	-	-	
Erosion Rills		V	4				-	-		
Slope Protection / Rip Rap		V	/				-	-	-	
Vegetation (greater than 12")		V	_				-			
DOWNSTREAM EMBANKMENT	General Condition	on: Go	ood	/ Fair / Poor	Repairs:	Date:				
Cracking			V						-	
Sloughing / Bulging			V				-		-	
Seepage			V							
Sink Holes		١	/						+-	
Sand Boils (indicate if flowing and color)		١					/	-	-	
Animal Burrows		/		Emoring 1 +	ورايادار		V	-	-	
Erosion Rills		١	/		ΜΑ				-	
Vegetation (greater than 12")			K	RECENTLY	Mowro			-	-	
SPILLWAY(S)	General Condition	1000		Fair / Poor	Repairs:	Date:	-	1		
Actively Flowing (provide depth)		1	V				_	-	-	
Obstructions Present			V				-	-	-	
Seepage			V				-	-	-	
Sand Boils (indicate if flowing and color)		-	V				_	-	-	
Erosion Rills		9	/							