CCR Impoundment Weekly Inspection 35 ILL, ADM, Code 845 / 40 CFR Part 257

	35 ILL. AL	JIVI. Code 845 / 40	J CFR Part 257	1 1 -
Station:	Kincaid		Date:	06/08/22
Impoundment Name:	Ash Pond		Time:	12:30 PM
IEPA Number:	W0218140002-01		Inspector(s):	D. Hubur
Sky: Crouse Temp.:	71° F Pr	ecip. (last 48 hrs):	0.67"	Pool Elev.:

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ACTION INVESTIGATE MONITOR DESCRIPTION YES NO SENT TO DSM ITEM Date: Repairs: CREST General Condition. Good / Fair / Poor Cracking Settlement V **Erosion Rills Animal Burrows** Misalignment Vegetation (greater than 12") UPSTREAM EMBANKMENT | General Condition: Good / Fair / Poor Repairs: Date: Cracking Sloughing / Bulging Seepage Sink Holes **Animal Burrows Erosion Rills** Slope Protection / Rip Rap Vegetation (greater than 12") Repairs: Date: DOWNSTREAM EMBANKMENT General Condition Good Fair / Poor Cracking Sloughing / Bulging Seepage Sink Holes Sand Boils (indicate if flowing and color) Finaing LILLING, **Animal Burrows Erosion Rills** Vegetation (greater than 12") General Condition: Good) Fair / Poor Repairs: Date: SPILLWAY(S) Actively Flowing (provide depth) V **Obstructions Present** V Seepage Sand Boils (indicate if flowing and color) **Erosion Rills**