CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Kincaid Date: 06/15/2 Impoundment Name: Ash Pond Time: 12:30 PM											
Station: Kind Impoundment Name: Ash F IEPA Number: W021814					Date:	06/15/		22	÷		
			a		Time:	12:3	o P	M	٠		
			4	Inspec	ctor(s):	II CONTRACTOR AND	немументовы	A CONTRACTOR OF THE PARTY OF TH			
total control of the	Transphiliphosparian and follows delicenses through the contraction		al .			Allowed the second second					
Sky: Sunny Temp.: 95°		P	recip. (last 48 hrs):	0.00			Pool Elev.			: -17 "	
YES" responses require description (si t the time of inspection. If "ACTION" dditional sheets as necessary. Circle (selected is "INVE	STIGAT	ΓΕ", please indicate dat	CRIPTION" section. se forwarded via em	"NO" respo ail to Dam S	nse indica afety Ma	ites no nager (DSM) .	Attach		
								ļ	CTIO	N	
ITEM		NO		DESCRIPTION				MONITOR	INVESTIGATE	SENT TO DSM	
CREST G	eneral Condition	. Good) Fair / Poor	Repairs:	Dá	ite:					
Cracking		V							ONE - IV		
Settlement		V									
Erosion Rills		1						***************************************			
Animal Burrows		V						_			
Misalignment		V.	- Lieuwen - Lieu								
Vegetation (greater than 12")		V									
UPSTREAM EMBANKMENT G	eneral Condition	Good	/ Fair / Poor	Repairs:	Da	ite:					
Cracking		[/		122200	10000000000000000000000000000000000000	Annual of Carallelon Million Property of Carallelon Property of Cara					
Sloughing / Bulging		V									
Seepage		V									
Sink Holes		V									
Animal Burrows		1		11							
Erosion Rills		1									
Slope Protection / Rip Rap		V									
Vegetation (greater than 12")		V									
OOWNSTREAM EMBANKMENT G	eneral Condition	Good	/)Fair / Poor	Repairs:	Da	ite:			14,5		
Cracking		ÌΖ	The state of the s				ya mga liki sibani Valadida	ATT THE REAL PROPERTY.	Hollowitherenther	***************************************	
Sloughing / Bulging		17									
Seepage		V									
Sink Holes		V									
Sand Boils (indicate if flowing an	id color)) /				1			
Animal Burrows	V	1	Finding 1	1/7レレントス				V			
Erosion Rills		V	0	Ü				• • • • • • • • • • • • • • • • • • • •			
Vegetation (greater than 12")	,	V		EXCITE TO THE PROPERTY OF THE							
	eneral Condition	Good	/ Fair / Poor	Repairs:	Da	ite:			· · ·		
Actively Flowing (provide depti		1/		THE RESERVE THE PROPERTY OF TH	202-0-0-10000-20000-00-00-00-00-00-00-00-00-00-00		raiding (Designation contract)	X (
Obstructions Present	-,	V	- Annual Company of the Company of t	ORDER DESIGNATION OF THE STREET							
Seepage		V									
Sand Boils (indicate if flowing an	d color)	V									
- 2.1.0 - 2.1.0 \ 1.1.0.00.00 II II V 1.1.1.B 011		_ <u></u>									

Erosion Rills