## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Stati	on: Kincaid	dk	Date:	07/06/22		
Impoundment Nar	ne: Ash Por	nd	Time:	: 1:30 PM		
IEPA Numk	er: W02181400	002-01	Inspector(s):	DAVE Huber		
Sky: Rain Ten	пр.: 77° F	Precip. (last 48 hrs):	0.40"	Pool Elev.: -19"		

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		101 00	DESCRIPTION		ACTION		
		NO			MONITOR	INVESTIGATE	SENT TO DSM
CREST Gen	eral Condition	Good	Fair / Poor Repairs:	Date:			
Cracking		7		V			
Settlement		V					
Erosion Rills		V					
Animal Burrows		1					
Misalignment		V					
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT Gen	eral Condition:	Good	/Fair / Poor Repairs:	Date:			
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Animal Burrows		V	.4				
Erosion Rills		V					
Slope Protection / Rip Rap		N					
Vegetation (greater than 12")		/					
DOWNSTREAM EMBANKMENT Gen	eral Condition	Good	/ Fair / Poor Repairs:	Date:			
Cracking		V					
Sloughing / Bulging		V					
Seepage		~					
Sink Holes		V,					
Sand Boils (indicate if flowing and color)		V					
Animal Burrows			Finaring / FIZLI	ing	V		
Erosion Rills		V	0	0			
Vegetation (greater than 12")		V					
SPILLWAY(S) Gen	eral Condition:	Good	/ Fair / Poor Repairs:	Date:			
Actively Flowing (provide depth)		V					
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)		V,					
Erosion Rills		V					