## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Kincai			Date:	07/13/22
Impoundment Name	Impoundment Name: Ash Pond		Time:	1400
IEPA Numbe	: W0218140002-0	1	Inspector(s):	D. Huben
Sky: CLEAN Temp	85°F	Precip. (last 48 hrs):	0.00	Pool Elev.: - 17 "

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM				DESCRIPTION		1	ACTION			
		YES	NO			MONITOR	INVESTIGATE	SENT TO DSM		
CREST	General Condit	rion	Good	Fair / Poor Repairs:	Date:					
Cracking			V							
Settlement			V							
Erosion Rills			/							
Animal Burrows			V							
Misalignment			V							
Vegetation (greater than 12")			V							
UPSTREAM EMBANKMENT	General Condit	ion(	Good	Fair / Poor Repairs:	Date:					
Cracking			V							
Sloughing / Bulging			V							
Seepage			V							
Sink Holes			V							
Animal Burrows			V	ď <sub>E</sub>						
Erosion Rills			V							
Slope Protection / Rip Rap			V							
Vegetation (greater than 12")			V							
DOWNSTREAM EMBANKMENT	Seneral Condit	tion:	Good	/ Fair / Poor Repairs:	Date:					
Cracking			V							
Sloughing / Bulging			V							
Seepage			V							
Sink Holes			1							
Sand Boils (indicate if flowing and color)			V							
Animal Burrows		/		Finging / Fixing		V		<u> </u>		
Erosion Rills			V	0.0						
Vegetation (greater than 12")			V							
SPILLWAY(S)	ieneral Condit	ion:	Good	/ Fair / Poor Repairs:	Date:	n -				
Actively Flowing (provide depth)			V		11					
Obstructions Present			V							
Seepage			V							
Sand Boils (indicate if flowing and color)			N							
Erosion Rills			V							