CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257						
		L. A	00/20/	21		
Station: Kinc	aid		Date: 01 (0)	77/2		
Impoundment Name: Ash P	ond		Time: $l:SO$	1 1		
IEPA Number: W021814	0002-	01	Inspector(s): 1). Hu	200		
Sky: CLEM Temp.: 91°			Pool		-16	8"
'YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.						
				-	CTIO	N
ITEM	YES	NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM
CREST General Conc	lition	ood	/ air / Poor Repairs: Date:			
Cracking		1				
Settlement		1				
Erosion Rills		J,				
Animal Burrows		/				
Misalignment		V,				
Vegetation (greater than 12")		V				
UPSTREAM EMBANKMENT   General Cond	lition: 0	Good	Fair / Poor Repairs: Date:			
Cracking		1				
Sloughing / Bulging		1				
Seepage		V.				
Sink Holes		1				
Animal Burrows		V	Ý.			
Erosion Rills		V				
Slope Protection / Rip Rap		1				
Vegetation (greater than 12")		~				
DOWNSTREAM EMBANKMENT General Cond	dition: C	bood	Fair / Poor Repairs: Date:			
0 11		1				

Cracking

Sloughing / Bulging

Seepage

Sink Holes

Sand Boils (indicate if flowing and color)

Animal Burrows

Erosion Rills

Cracking

Animal Embankment General Condition: Good / Fair / Poor Repairs: Date:

Repairs: Date:

Repairs: Date:

Repairs: Date:

Repairs: Date:

Repairs: Date:

Physical Repairs: Date:

Physical Repairs: Date:

Repairs: Date:

Repairs: Date:

Physical Repairs: Date:

SPILLWAY(S) General Condition Good Fair / Poor Repairs: Date:

Actively Flowing (provide depth)

Obstructions Present

Seepage
Sand Boils (indicate if flowing and color)
Erosion Rills

Vegetation (greater than 12")