CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Kincaid			Date:	08/17/22	
Impoundment Name:	Ash Pond		Time:	12:45 PM	
IEPA Number:	W0218140002-0	1	Inspector(s):	D. Huben	
Sky: CLYAL Temp.:	81°F	Precip. (last 48 hrs):	0.00"	Pool Elev.:	-23"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM			DESCRIPTION		ACTION		
		NO			MONITOR	INVESTIGATE	SENT TO DSM
CREST General C	Condition		Fair / Poor Repairs:	Date:			
Cracking		V	4	1			
Settlement		1					
Erosion Rills		V					
Animal Burrows		V					
Misalignment		V		k U			
Vegetation (greater than 12")		-					
UPSTREAM EMBANKMENT General C	ondition	Good	Fair / Poor Repairs:	Date:			
Cracking))	V					
Sloughing / Bulging		1					
Seepage		V					
Sink Holes		V					
Animal Burrows		V	N				
Erosion Rills		V					
Slope Protection / Rip Rap		V					
Vegetation (greater than 12")		V				<u> </u>	
DOWNSTREAM EMBANKMENT General C	ondition:	Good	Fair / Poor Repairs:	Date:			
Cracking		V					
Sloughing / Bulging		1					
Seepage		V					
Sink Holes		/					
Sand Boils (indicate if flowing and color)		V					
Animal Burrows		V			,		
Erosion Rills			Finding a Filling	ng	V		
Vegetation (greater than 12")		V	· · ·	V			
SPILLWAY(S) General Co	ondition	Good	Fair / Poor Repairs:	Date:			
Actively Flowing (provide depth)		V					
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)		V					
Erosion Rills		1	9				