	(CCR Imp	ooundment Weekl	/ Inspection				
	35	5 ILL. A	OM. Code 845 / 40	CFR Part 257	10.1	7 81		
Station: Kincaid					Date: 08/31	11		
Impoundment Name: Ash Pond					Time: 12:00	PM		
Impoundment Name:			Inspec	tor(s): 1) . I+ wb	los			
				224			1	7 4 11
Sky: CLEAR Temp.:	79° F	P	recip. (last 48 hrs):	0.33	Pool	l Elev.:	-11	7.6
"YES" responses require description (size, depth, exter	nts, color) and location in "DESC	RIPTION" section.	"NO" response indicates no	issues v	vere obs	served
at the time of inspection. If "ACTION	l" selected is "INV	/ESTIGAT	E, please mulcate date	forwarded via em	ail to Dam Safety Manager	(DSM).	Attacn	
additional sheets as necessary. Circle	e General Conditi	on for ea	ch section.				CTION	d l
ITEM		ES NO	DESC	DESCRIPTIO	CRIPTION		INVESTIGATE	0
		ES NO	DEGGMI III		MONITOR	/EST	SENT TO DSM	
						Σ	Z	SEI
CREST	General Condition	on Good	/ Fair / Poor	Repairs:	Date:			
Cracking		1			12			
Settlement		V	_					
Erosion Rills		V				-		
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT	General Condition	on: Good	Fair / Poor	Repairs:	Date:			
Cracking		V				-		
Sloughing / Bulging		V				_		
Seepage		V				_		
Sink Holes		V					-	
Animal Burrows		V	_	t .			-	
Erosion Rills		V				-	+	
Slope Protection / Rip Rap)	V				-	-	

Vegetation (greater than 12")

DOWNSTREAM EMBANKMENT General Condition: Good Fair / Poor Repairs: Date:

Cracking

Sloughing / Bulging

Seepage

Sink Holes

Sand Boils (indicate if flowing and color)

Animal Burrows

Date:

Vegetation (greater than 12")

SPILLWAY(S)

General Condition: Good / Fair / Poor

Repairs:

Actively Flowing (provide depth)

Obstructions Present

Seepage

Sand Boils (indicate if flowing and color)

Erosion Rills