## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

			-0/0/27
Station:	Kincaid	Date:	09/21/22
Impoundment Name:	Ash Pond	Time:	1:30 PM
IEPA Number:	W0218140002-01	Inspector(s):	D. Hubler
Sky: CLOUSY Temp.:	88° F Precip. (last 48 hrs):	6.00"	Pool Elev.:12.0"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sheets as necessary. Circle General Con		S NO			ACTION			
			DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM		
CREST General Co.	ndition	Good	/ Fair / Poor Repairs: Date:					
Cracking		V						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		V				-		
UPSTREAM EMBANKMENT General Con	ndition:	6000	Fair / Poor Repairs: Date:					
Cracking		V		1				
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V				-		
Animal Burrows		V	6			<u> </u>		
Erosion Rills		V						
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")		V	5					
DOWNSTREAM EMBANKMENT General Con	ndition:	Good	Fair / Poor Repairs: Date:					
Cracking		7						
Sloughing / Bulging		V	V -					
Seepage		V	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
Sink Holes		V						
Sand Boils (indicate if flowing and color)		/						
Animal Burrows			Finding / Filling	V				
Erosion Rills		V	0					
Vegetation (greater than 12")		V						
SPILLWAY(S) General Cor	ndition:	Good	/ Fair / Poor Repairs: Date:	2.4				
Actively Flowing (provide depth)		7						
Obstructions Present		V				ļ		
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		V						