CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	35 ILL.	ADM. Code 845 / 40	O CFR Part 257	1 2 1 2 2
Station:	Kincaid		Date:	10/19/14
Impoundment Name:	Ash Pond	= .	Time:	1:30 PM
IEPA Number:	W0218140002-01		Inspector(s):	1). Hugur
Sky: CLEAN Temp.:	49° F	Precip. (last 48 hrs):	0.00"	Pool Elev.: -15 h

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		1	ACTION		
					MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Co	ndition;	Good	Fair / Poor	Repairs:	Date:			
Cracking		V						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT General Co	ndition:	Good	Fair / Poor	Repairs:	Date:			
Cracking	23	V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Animal Burrows		V		9				
Erosion Rills		V						
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")		x						
DOWNSTREAM EMBANKMENT General Co	ndition	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		V						
Sloughing / Bulging		V,						
Seepage		V						
Sink Holes		V						
Sand Boils (indicate if flowing and color)		V		1_		/		
Animal Burrows			Finoring	x/ Firing		V		
Erosion Rills		1		,	20-11			
Vegetation (greater than 12")		V	¥ - V					
SPILLWAY(S) General Co	ndition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)		V						
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		V						