CCR Impoundment Weekly Inspection

	35 ILL.	ADM. Code 845 / 40	CFR Part 257	1)	
Station:	Kincaid		Date:	11/09/22	
Impoundment Name:	Ash Pond		Time:		
IEPA Number:	W0218140002-01		Inspector(s):		
Sky: Sunny Temp.:	75°F	Precip. (last 48 hrs):	0.00"	Pool Elev.:	-10"
YES" responses require description (it the time of inspection. If "ACTION idditional sheets as necessary. Circle	l" selected is "INVESTIGA	ATE", please indicate date	(IPTION" section. "NO" resp forwarded via email to Dam	oonse indicates no issues w 1 Safety Manager (DSM)	vere observed Attach
additional shoots as his section (A	CTION
					ূ 변

NVESTIGA YES NO DESCRIPTION ITEM Repairs: Date: General Condition Good / Fair / Poor CREST Cracking Settlement **Erosion Rills Animal Burrows** Misalignment Vegetation (greater than 12") UPSTREAM EMBANKMENT General Condition Good Fair / Poor Repairs: Date: Cracking Sloughing / Bulging V Seepage Sink Holes **Animal Burrows Erosion Rills** Slope Protection / Rip Rap Vegetation (greater than 12") DOWNSTREAM EMBANKMENT | General Condition, Good | Fair / Poor Date: Repairs: Cracking Sloughing / Bulging Seepage Sink Holes Sand Boils (indicate if flowing and color) **Animal Burrows Erosion Rills** Vegetation (greater than 12") Date: SPILLWAY(S) General Condition: Good / Fair / Poor Repairs: Actively Flowing (provide depth) **Obstructions Present** V V Seepage Sand Boils (indicate if flowing and color) **Erosion Rills**