	;	CCF 35 IL	R Imp L. Al	ooundment Week DM. Code 845 / 40	The contract of the contract o		11/11/2	2			
Station:	Station: Kincaid			Date: 11/16/02							
Impoundment Name: Ash Pond						Time:	1130 P	7			
IEPA Number: W0218140			-01		Inspe	ctor(s):	D- Hube	u_		G/	
Sky: Crousy Temp.: 31° F			P	recip. (last 48 hrs):			11/16/22 : 1:30 PM : D. Hubur Pool Elev.:			-16"	
"YES" responses require description at the time of inspection. If "ACTION additional sheets as necessary. Circle	l" selected is "li	AAF2	HUGAI	E, please maleace day	CRIPTION" section. e forwarded via en	"NO" respo nail to Dam S	nse indicates no afety Manager		Attach		
ITEM		YES			DESCRIPTIC	N		MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Condi	tion:	good	Fair / Poor	Repairs:	D	ate:				
Cracking			V				157	-	-	-	
Settlement			V					+	-		
Erosion Rills			V					-	-		
Animal Burrows		I	V						-	-	
Misalignment			V					+	-		
Vegetation (greater than 12")		X					+	+	-	
UPSTREAM EMBANKMENT	General Cond	ition	Goog	// Fair / Poor	Repairs:		ate:			+	
Cracking	2		V							-	
Sloughing / Bulging			V					+	-	-	
Seepage			V								
Sink Holes			/		PV .			-			
Animal Burrows			1		•			-			
Erosion Rills			V					+			

Fraging

General Condition. Good / Fair / Poor

V

V

V

Date:

Date:

Repairs:

Repairs:

Slope Protection / Rip Rap Vegetation (greater than 12")

Sand Boils (indicate if flowing and color)

Vegetation (greater than 12")

Actively Flowing (provide depth)

Sand Boils (indicate if flowing and color)

SPILLWAY(S)

Obstructions Present

Sloughing / Bulging

Animal Burrows Erosion Rills

Cracking

Seepage Sink Holes

Seepage

Erosion Rills

DOWNSTREAM EMBANKMENT General Condition: Good / Fair / Poor