CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	11/30/22				
Station:	Kincaid		Date:	11/30/16	
Impoundment Name:	Ash Pond		Time:	10:30 AM	
IEPA Number:	W0218140002-01		Inspector(s):	1. Hugur	
Sky: P. Sunny Temp.:	31°F P	recip. (last 48 hrs):	0.01"	Pool Elev.:	-18"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sheets as necessary. Chele denotal de	T					1	ACTION		
ITEM		NO	DESCRIPTION			MONITOR	INVESTIGATE	SENT TO	
CREST General Cor	dition	Good	Fair / Poor	Repairs:	Date:				
Cracking		V	,					-	
Settlement		V						-	
Erosion Rills		V						-	
Animal Burrows		V						-	
Misalignment		V							
Vegetation (greater than 12")		V						-	
UPSTREAM EMBANKMENT General Cor	dition:	Good	Fair / Poor	Repairs:	Date:				
Cracking		7						-	
Sloughing / Bulging		V							
Seepage		V					_		
Sink Holes		V				_		-	
Animal Burrows		V		3 r					
Erosion Rills		V				_		-	
Slope Protection / Rip Rap		V						-	
Vegetation (greater than 12")		V						-	
DOWNSTREAM EMBANKMENT General Cor	dition	Good	/ Fair / Poor	Repairs:	Date:			-	
Cracking		V			1/2			-	
Sloughing / Bulging		V						-	
Seepage		V						-	
Sink Holes		V						-	
Sand Boils (indicate if flowing and color)		V		1		V	_	-	
Animal Burrows	V		Franco	g/ Filling		V		-	
Erosion Rills		V		0					
Vegetation (greater than 12")	45	2						-	
	dition:	Good	/ Fair / Poor	Repairs:	Date:			+	
Actively Flowing (provide depth)		1							
Obstructions Present		V					-		
Seepage		V				_	-	-	
Sand Boils (indicate if flowing and color)		V							
Erosion Rills		V			*				