			oundment weekly in					
	35 IL	L. A	OM. Code 845 / 40 CF	R Part 257	10/1/2	.2		
Station: Kincaid					Date: ///			
				Time:				
				Inspect	or(s): D. Hus	un	,	
				0"			-1	7"
Sky: Clouse Temp.: 51	F	Pi	recip. (last 48 hrs):	0	Pool	Elev.:	-	_
"YES" responses require description (size, depth,	extents	, color) and location in "DESCRIPT	TION" section. "	NO" response indicates no	issues v	vere ob	served
at the time of inspection. If "ACTION" selected is	"INVES	TIGAT	E", please indicate date for	warded via ema	Il to Dam Safety Manager (DSIVI) .	ALLacii	
additional sheets as nècessary. Circle General Co	ndition	for ea	ch section.				CTION	THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.
							11	
	VEC	NO		DESCRIPTION		OR	IIGA	0
ITEM	YES	NO				MONITOR	VEST	SENT 1 DSM
						M	2	SE
CREST General Cor	ndition.	Good	Fair / Poor Re	epairs:	Date:		-	
Cracking	T	V						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		1			Data		The real Property	
UPSTREAM EMBANKMENT General Con	ndition	Good	Fair / Poor Re	epairs:	Date:	Annual An	Non-Confedence	The same of
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		N		1,				
Animal Burrows		1						
Erosion Rills		-						
Slope Protection / Rip Rap		N						
Vegetation (greater than 12").	11.1	NA.	/ Fair / Door R	epairs:	Date:		11 20	
DOWNSTREAM EMBANKMENT General Con	ndition	G000	// Fair / Pool	cpuiis.				
Cracking		V						
Sloughing / Bulging		1						
Seepage		V						
Sink Holes		1/				1		
Sand Boils (indicate if flowing and color)	1	-	Finary LF11	un		V		
Animal Burrows	V	1	1 10000					

Date:

Repairs:

Vegetation (greater than 12")

Actively Flowing (provide depth)

Sand Boils (indicate if flowing and color)

SPILLWAY(S)

Obstructions Present

General Condition: Good Fair / Poor

Erosion Rills

Seepage

Erosion Rills