CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	00 144.			12 122 122
Station:	Kincaid		Date:	12/02/22
Impoundment Name:	Ash Pond		Time:	16 11/1
IEPA Number:	W0218140002-01		Inspector(s):	D. Husun
Sky: CLBY Temp.:	20°F Pro	ecip. (last 48 hrs):	0.0	Pool Elev.: -15"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sheets as necessary. Circle General Con		T	NO	DESCRIPTION		ACTION		
		ES I				MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condition:		ood	Fair / Poor Repairs:	Date:			
Cracking			V	,				
Settlement			V			-		
Erosion Rills			V			-		
Animal Burrows			V			-		-
Misalignment			V					
Vegetation (greater than 12")			V			-		-
UPSTREAM EMBANKMENT		n:(G	ood	Fair / Poor Repairs:	Date:			-
Cracking	5		V					
Sloughing / Bulging			V					-
Seepage			V					-
Sink Holes			V			-		-
Animal Burrows			1	Y (
Erosion Rills			V					-
Slope Protection / Rip Ra	р		V					-
Vegetation (greater than 12").			V			-		
DOWNSTREAM EMBANKMENT	General Condition	n:(6	ood	/ Fair / Poor Repairs:	Date:			
Cracking			V			-	-	-
Sloughing / Bulging			V			-		-
Seepage			V			-	-	
Sink Holes			V					
Sand Boils (indicate if flowing and color)			V	16:		1		
Animal Burrows		/		Finging / Hillian		V		-
Erosion Rills			V	0	/			-
Vegetation (greater than 12")			V	. '				
SPILLWAY(S)	General Condition	n:(G	lood	/ Fair / Poor Repairs:	Date:		ļ	-
Actively Flowing (provide depth)			V					-
Obstructions Present			V			-		-
Seepage			V			-		-
Sand Boils (indicate if flowing and color)			V		3			
Erosion Rills			V	é	*			