			poundment Weekl	y Inspection					
8	35 I	LL. A	DM. Code 845 / 40	CFR Part 257	2 10	2/20			
Station:	8800				Date: 12/2	8/11	,		
Impoundment Name:				*	Date: 12/28/22 Time: 12:30 Pry Inspector(s): D. Huban				
	W0218140002-01		3	Inspector(s): D. Huban					
70					h		15	14	
			recip. (last 48 hrs):	0.00		Pool Elev.:		7	
"YES" responses require description of at the time of inspection. If "ACTION additional sheets as necessary. Circle	" selected is "INVES	STIGAT	TE", please indicate date	CRIPTION" section. " e forwarded via ema	NO" response indic il to Dam Safety M				
						/	ACTION		
ITEM	YES	NO		DESCRIPTION	I	MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Condition	Good	Fair / Poor	Repairs:	Date:				
Cracking		V						_	
Settlement		V						-	
Erosion Rills		V					_	-	
Animal Burrows		V					_	-	
Misalignment		V							
Vegetation (greater than 12")		V		1			-	+	
UPSTREAM EMBANKMENT	General Condition	Good	/ Fair / Poor	Repairs:	Date:		-	+-	
Cracking	R	V							
Sloughing / Bulging		V							
Seepage		V		N "			-	+-	
Sink Holes		V					-	+	
Animal Burrows		N		* 1			-	+-	
Erosion Rills		V					+-	-	
Slope Protection / Rip Rap		1					+-	+	

Date:

Date:

Repairs:

Repairs:

Vegetation (greater than 12")

Vegetation (greater than 12")

Actively Flowing (provide depth)

Sand Boils (indicate if flowing and color)

SPILLWAY(S)

Obstructions Present

Sand Boils (indicate if flowing and color)

Sloughing / Bulging

Animal Burrows Erosion Rills

Cracking

Seepage Sink Holes

Seepage

Erosion Rills

DOWNSTREAM EMBANKMENT General Condition Good Fair / Poor

General Condition: Good Fair / Poor

V