				-				4	
		CCI	R Im	poundment Weekl	y Inspection				
	;	35 II	LL. Al	DM. Code 845 / 40	CFR Part 257	1	22		
Station: Kinca			aid Date: 01/04						
Impoundment Name: Ash Po					₽	Time: 11:45 /	try		
	IEPA Number: W0218140				ctor(s):0. Hus	D. Hursen			
Sky: Crousy Temp.:	38° F	-	Р	recip. (last 48 hrs):	1.10"		Elev.:	-13	3.0"
'YES" responses require description (at the time of inspection. If "ACTION additional sheets as necessary. Circle	I" selected is "IN	NVES	TIGAT	E", please indicate date	RIPTION" section. forwarded via em	"NO" response indicates no ail to Dam Safety Manager (7,000,071	
, additional of the same of th							/2	CTIO	4
ITEM		YES	NO		DESCRIPTIO	<i>N</i> .	MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condit	ion(Good	Fair / Poor	Repairs:	Date:			
Cracking		-	Y						
Settlement			V						
Erosion Rills			/						
Animal Burrows			V						
Misalignment			V						
Vegetation (greater than 12")			V		7				
UPSTREAM EMBANKMENT	General Condit	tion:		Fair / Poor	Repairs:	Date:			
Cracking	*		V						
Sloughing / Bulging			V						
Seepage			V						
Sink Holes			V		3 ,				
Animal Burrows			V		# I				

Erosion Rills Slope Protection / Rip Rap Vegetation (greater than 12") DOWNSTREAM EMBANKMENT | General Condition: Good | Fair / Poor Repairs: Date: Cracking Sloughing / Bulging Seepage Sink Holes Sand Boils (indicate if flowing and color) **Animal Burrows Erosion Rills** Vegetation (greater than 12") Date: General Condition. Good / Fair / Poor Repairs: SPILLWAY(S) Actively Flowing (provide depth) **Obstructions Present**

Seepage

Erosion Rills

Sand Boils (indicate if flowing and color)