## CCR Impoundment Weekly Inspection

	20 ILL.	ADIVI. CODE 643 / 40	GITT OT CAS.	1 2 2	
Station:	Kincaid		Date:	01/11/63	
Impoundment Name:	Ash Pond		· Time:	1230	
IEPA Number:	W0218140002-01		Inspector(s):	D. Huber	
Sky: Sunny Temp.:	60°F	Precip. (Jast 48 hrs):	6.00"	Pool Elev.:	)

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION		
					MONITOR	INVESTIGATE	SENT TO
CREST Genera	I Condition(	Good	/ Fair / Poor Repairs:	Date:			
Cracking		V	7	10	_		
Settlement		V					<u> </u>
Erosion Rills		V					-
Animal Burrows		V					
Misalignment		V		and the second s			
Vegetation (greater than 12")		8			-	-	┼
UPSTREAM EMBANKMENT Genera	I Condition	Good	/ Fair / Poor Repairs:	Date:			<u> </u>
Cracking		V					
Sloughing / Bulging		V					_
Seepage		V		and mile distribution in the control of the control		_	+-
Sink Holes		V		3	_	-	+-
Animal Burrows		V	F C .				-
Erosion Rills		/				-	+-
Slope Protection / Rip Rap		V	3 6			-	-
Vegetation (greater than 12")		V				ļ	-
DOWNSTREAM EMBANKMENT Genera	l Condition:	Good	Fair / Poor Repairs:	Date:		-	-
Cracking		7		1	_	-	-
Sloughing / Bulging		V				<u> </u>	
Seepage		1		and the second s			-
Sink Holes		V			_		-
Sand Boils (indicate if flowing and color)		1				-	-
Animal Burrows		1	Finding Filling		V	-	-
Erosion Rills		/	· · ·	and the second s			
Vegetation (greater than 12")		V				-	-
	l Condition:	Good	/ Fair / Poor Repairs:	Date:		-	-
Actively Flowing (provide depth)		1			_	-	-
Obstructions Present		1				-	-
Seepage		V					-
Sand Boils (indicate if flowing and color)		V					-
Erosion Rills		V					