			poundment Week	49.00					
	35	ILL. A	DM. Code 845 / 40	CFR Part 257	10-10			19	
Station: Kincaid				Date: 01/25/23		- 5	ı		
Impoundment Name: Ash Pond		k	í	*	Time: 1:90 P	m			
IEPA Number: W0218140002-		02-01	•	Date: 0/25/23 Time: 1:90 PM Inspector(s): D. Hubak					
E				1)			1	6 ()	
Sky: CLOUSY Temp.: 35°F		Precip. (last 48 hrs):							
"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.									
ITEM		JII TOT CO	l section.				ACTION		
		S NO	DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM		
CREST General Condition			Fair / Poor	Repairs:	Date:				
Cracking	,	V							
Settlement		V							
Erosion Rills		V							
Animal Burrows		1						_	
Misalignment		V	·					-	
Vegetation (greater than 12")		V				-		-	
	General Conditio	ny Good	Fair / Poor	Repairs:	Date:				
Cracking		V							
Sloughing / Bulging		~						-	
Seepage		V				-			
Sink Holes		~				-	-		
Animal Burrows		1		J. 1		-	-		
Erosion Rills		1					-	-	
Slope Protection / Rip Rap		~	3			+	-	\vdash	
Vegetation (greater than 12")		V				-			
DOWNSTREAM EMBANKMENT	General Condition	n: Good	Fair / Poor	Repairs:	Date:				

Cracking Sloughing / Bulging Seepage Sink Holes Sand Boils (indicate if flowing and color) **Animal Burrows Erosion Rills** Vegetation (greater than 12") General Condition: Good/Fair/Poor Date: Repairs: SPILLWAY(S) V Actively Flowing (provide depth) **Obstructions Present** V Seepage V Sand Boils (indicate if flowing and color) **Erosion Rills**