CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

| Station: Kincaid | Date: 02/22/23 | Time: 12:30 PM | Inspector(s): D-1-when | Sky: PAN | Temp.: 51° F | Precip. (last 48 hrs): 0.56" | Pool Elev.: -13.0"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

| ITEM | | NO | DESCRIPTION | | | ACTION | | |
|--|------------|------|--|----------------------|--|---------|-------------|----------|
| | | | | | | MONITOR | INVESTIGATE | SENT TO |
| CREST General C | ondition: | Good | /Fair / Poor | Repairs: | Date: | | | |
| Cracking | 1 | V | and the state of t | | | | | |
| Settlement | | V | | | | | | <u> </u> |
| Erosion Rills | | 1 | | | | | | |
| Animal Burrows | 1 | V | | | | | | |
| Misalignment | | V | | | | _ | | <u> </u> |
| Vegetation (greater than 12") | | X | \ | | | _ | - | - |
| UPSTREAM EMBANKMENT General C | ondition | Good | Fair / Poor | Repairs: | Date: | | | - |
| Cracking | | V | | eller and the second | | | | <u> </u> |
| Sloughing / Bulging | | N | | | | | | - |
| Seepage | | V | | | | | - | - |
| Sink Holes | | V | | | | | | - |
| Animal Burrows | | V | | 3 C ₁ | | | - | ├ |
| Erosion Rills | | V | | | | _ | <u> </u> | - |
| Slope Protection / Rip Rap | | V | 11 | | | | | - |
| Vegetation (greater than 12") | | 1 | | | | | | - |
| DOWNSTREAM EMBANKMENT General C | ondition: | Good | Fair / Poor | Repairs: | Date: | | - | - |
| Cracking | | A | | | | | <u> </u> | - |
| Sloughing / Bulging | | V | | | | | | - |
| Seepage | | V | | | The state of the s | | - | - |
| Sink Holes | | V | | | | | - | - |
| Sand Boils (indicate if flowing and color) | | V | | | | | - | + |
| Animal Burrows | V | | | | | | - | - |
| Erosion Rills | | V | | | 41-2-100(19) | | - | - |
| Vegetation (greater than 12") | | V | | | | | - | - |
| SPILLWAY(S) General C | Condition: | 6000 | / Fair / Poor | Repairs: | Date: | + | +- | - |
| Actively Flowing (provide depth) | | V | | | | | | - |
| Obstructions Present | | V | | | | | - | - |
| Seepage | | V | 1 | | | | - | - |
| Sand Boils (indicate if flowing and color) | | N | A | | | | - | - |
| Erosion Rills | | 1 | | * | * | | | |