CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid		Date:	7 A
Impoundment Name:	Ash Pond		Time:	
IEPA Number:	W0218140002-01		Inspector(s):	1). Hub en
Sky: Crousy Temp.:	41°F	Precip. (last 48 hrs):	0.21"	Pool Elev.: - 15 "

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		1	DESCRIPTION		ACTION		
		NO			MONITOR	INVESTIGATE	SENT TO
CREST Ge	neral Condition	Good	Fair / Poor Repairs:	Date:			
Cracking		V			ļ		
Settlement		V			ļ		<u> </u>
Erosion Rills		V		- ye	<u> </u>		
Animal Burrows		V			-		
Misalignment		V			ļ		
Vegetation (greater than 12")		1					-
UPSTREAM EMBANKMENT Ge	neral Condition	Good	Fair / Poor Repairs:	Date:			
Cracking		V					ļ
Sloughing / Bulging		1			<u> </u>		
Seepage		V			_		-
Sink Holes		V			-		-
Animal Burrows		1	1 C.4.				-
Erosion Rills		V					_
Slope Protection / Rip Rap		V	S		-	-	↓
Vegetation (greater than 12")		1			ļ	ļ	-
DOWNSTREAM EMBANKMENT GE	neral Condition	: Good	/ Fair / Poor Repairs:	Date:			-
Cracking		V					-
Sloughing / Bulging		V					-
Seepage		1			-		_
Sink Holes		1			1-	_	├-
Sand Boils (indicate if flowing and color)		V			/	-	-
Animal Burrows			Finding / till	1N5)	-		├_
Erosion Rills		V		V	-		-
Vegetation (greater than 12")		V	:		-		
SPILLWAY(S) Ge	eneral Condition	: 6000	Fair / Poor Repairs:	Date:	-	-	-
Actively Flowing (provide depth)		V				-	-
Obstructions Present		V			-	-	-
Seepage		V		www.	ļ	-	├
Sand Boils (indicate if flowing and color)		1			-	-	-
Erosion Rills		V	ive:	•	L		