				ekly Inspection				
	35 IL	L. Al	DM. Code 845 /	40 CFR Part 257	- 1 1	- 2		
Station:	Kincaid				Date: 03/29/	23		
Impoundment Name: A	ndment Name: Ash Pond			₽	Time: //30 P	M		
IEPA Number: W0218140002		-01		Inspec	Date: 03/29/ Time: //30 P ctor(s): 7) . HWb	w		
3		-		0.02	1)		W-1	, 11
Sky: P. Crousy Temp .: 4			recip. (last 48 hrs) o				4.0"
"YES" responses require description (size, dep at the time of inspection. If "ACTION" selecte additional sheets as necessary. Circle Genera	d is "INVES"	TIGAT	E", please indicate	ESCRIPTION" section. date forwarded via em	"NO" response indicates no ail to Dam Safety Manager	issues v (DSM) .	vere ok Attach	oserved
auditional should be independent of the control of						1	CTIO	N
ITEM	YES	NO		DESCRIPTION	N	MONITOR	INVESTIGATE	SENT TO DSM
CREST General	Condition	- nord	Fair / Poor	Repairs:	Date:			
	Condition		7		1 × 1 × 1 × 1 × 1 × 1 × 1 × 1 × 1 × 1 ×			
Cracking		1			The state of the s			
Settlement		7						
Erosion Rills Animal Burrows		V		10-1-10-10-10-10-10-10-10-10-10-10-10-10				
Misalignment		V						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT General	Condition	Good	Fair / Poor	Repairs:	Date:			
Cracking		1						
Sloughing / Bulging		1						
Seepage		V						
Sink Holes		V						
Animal Burrows		V		1.7.6				
Erosion Rills		1						
Slope Protection / Rip Rap		V			- LAND			
Vegetation (greater than 12").		X						
DOWNSTREAM EMBANKMENT General	Condition:	Good	Fair / Poor	Repairs:	Date:			
Cracking		1				1		
Sloughing / Bulging		V				-		

Date:

Repairs:

Seepage Sink Holes

Seepage

Erosion Rills

Animal Burrows Erosion Rills

Vegetation (greater than 12")

Actively Flowing (provide depth)

Sand Boils (indicate if flowing and color)

SPILLWAY(S)

Obstructions Present

Sand Boils (indicate if flowing and color)

General Condition: Good Fair / Poor