CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

		ADIVI. GOAC G IS / IS S		04/08/23	
Station:	Kincaid	_	Date:	04 05 (2)	
Impoundment Name:	Ash Pond	_	· Time:	1:40 PM	
IEPA Number:	W0218140002-01		Inspector(s):	1). Hublin	n)
Sky: Clousy Temp.:	5101	Precip. (last 48 hrs):	0.00	Pool Elev.:	-16.0"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

						/2	CTIO	N
ITEM		NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO
CREST General Con	dition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		V	The state of the s					-
Settlement		V						
Erosion Rills		/						-
Animal Burrows		V						-
Misalignment		V		*				-
Vegetation (greater than 12")		V						-
UPSTREAM EMBANKMENT General Con	dition:	Good	/ Fair / Poor	Repairs:	Date:			-
Cracking		V						<u> </u>
Sloughing / Bulging		V						-
Seepage		V						-
Sink Holes		V						-
Animal Burrows		1		1 r g				├-
Erosion Rills		V						-
Slope Protection / Rip Rap		V				_	-	-
Vegetation (greater than 12")		1						-
DOWNSTREAM EMBANKMENT General Cor	dition:	Good	/ Fair / Poor	Repairs:	Date:			-
Cracking		V					-	-
Sloughing / Bulging		V						ļ
Seepage		V			1400			-
Sink Holes		V			- Alexander -		-	-
Sand Boils (indicate if flowing and color)		V				1		┼
Animal Burrows			1-1200	7 FILLING		V		-
Erosion Rills		V			Samuel III and Samuel			-
Vegetation (greater than 12")		V					ļ	-
SPILLWAY(S) General Cor	ndition:	66od	Fair / Poor	Repairs:	Date:		_	-
Actively Flowing (provide depth)		V					Maria di Santa di San	-
Obstructions Present		V						-
Seepage		V					_	-
Sand Boils (indicate if flowing and color)		V					_	-
Erosion Rills		V						