## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Date: 05/03/13

Station: Kincaid

Impoundment Name: Ash Pond

IEPA Number: W0218140002-01

Time: 1:30 PM
Inspector(s): D. Hub Cr.

Sky: CLEAR

Temp.: 75°F

Precip. (last 48 hrs):

0.00

Pool Elev .: - 16.0

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		1	DESCRIPTION		1	ACTION		
		S NO			MONITOR	INVESTIGATE	SENT TO	
CREST Ger	neral Condition	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		V				_		
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		V						-
UPSTREAM EMBANKMENT Ger	neral Conditio	n: Good	i Fair / Poor	Repairs:	Date:			
Cracking	5	V			<i>n</i>			
Sloughing / Bulging		V						
Seepage		V					-	-
Sink Holes		V						
Animal Burrows		V		* (1 a	The second secon		-	-
Erosion Rills		V					-	<u> </u>
Slope Protection / Rip Rap		V	4				-	
Vegetation (greater than 12")		V						<u> </u>
DOWNSTREAM EMBANKMENT Ger	neral Conditio	n: <b>G</b> ood	Fair / Poor	Repairs:	Date:			-
Cracking		V						
Sloughing / Bulging		V		-		_		
Seepage		V					-	
Sink Holes		1					_	<u> </u>
Sand Boils (indicate if flowing and	color)	V		10		-		-
Animal Burrows	V		France	3 Freeze		V	-	-
Erosion Rills		V		U				-
Vegetation (greater than 12")		V		1				-
SPILLWAY(S) Ger	neral Conditio	n: <b>6</b> 000	/ Fair / Poor	Repairs:	Date:			-
Actively Flowing (provide depth)		V				_		
Obstructions Present		V				_		<b>}</b>
Seepage		V						<del> </del>
Sand Boils (indicate if flowing and	color)	V						
Erosion Rills		V		÷	1.50			