CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	35 ILL. A	DM. Code 845 / 40	CFR Part 25/		120	
Station:	Kincaid		Date:	05/10	123	ı.
Impoundment Name:	Ash Pond	-	· Time:	2:95	PM	Ē
IEPA Number:	W0218140002-01	=	Inspector(s):	D. Hu	bur	1
Sky: Suny Temp.:	72°F	Precip. (last 48 hrs):	0.60"	Po	ol Elev.:	-16"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		10, 60				1	ACTION		
		NO	DESCRIPTION		MONITOR	INVESTIGATE	SENT TO		
CREST G	eneral Condition	Good	/Fair / Poor	Repairs:	Date:				
Cracking		V	,						
Settlement		1							
Erosion Rills		1							
Animal Burrows		V			The second secon			-	
Misalignment		V		*				-	
Vegetation (greater than 12")		1							
UPSTREAM EMBANKMENT G	eneral Condition	:Good	Fair / Poor	Repairs:	Date:				
Cracking	-61	V					ļ	-	
Sloughing / Bulging		1							
Seepage		1			· · · · · · · · · · · · · · · · · · ·	-	-	-	
Sink Holes		1				-			
Animal Burrows		1		EA J					
Erosion Rills		/				-	-	-	
Slope Protection / Rip Rap		V	3			-	-	-	
Vegetation (greater than 12")		V						-	
DOWNSTREAM EMBANKMENT	ieneral Condition	: Good	/ Fair / Poor	Repairs:	Date:	_			
Cracking		V			A STATE OF THE STA		-	-	
Sloughing / Bulging		V				_		-	
Seepage		V							
Sink Holes		V					-	-	
Sand Boils (indicate if flowing ar	nd color)	. ~		16		-	1	-	
Animal Burrows	V		FINONE	Trurng		V	-	-	
Erosion Rills		V		V		_	-	-	
Vegetation (greater than 12")	6	V		and the second s			<u> </u>		
SPILLWAY(S)	General Condition	: 6000	/ Fair / Poor	Repairs:	Date:	-	-	-	
Actively Flowing (provide dept	h)	V		· ·		_	ļ		
Obstructions Present		V					-	-	
Seepage		V				-	-	<u> </u>	
Sand Boils (indicate if flowing and color)		V		The second secon		_	ļ	-	
Erosion Rills		V		3	¥				