CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	33 ILL.	ADIVI. COUR 043 / 40 CIT	N CH C LLC	12.122	
Station:	Kincaid	_	Date:	05/24/23	
Impoundment Name:	Ash Pond		· Time:	1:30 PM	
IEPA Number:	W0218140002-01	_	Inspector(s)	D. Huben	
Sky: CLEAR Temp.:	82°F	Precip. (last 48 hrs):	0.0"	Pool Elev.:	-16"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		1-	ACTION		
					MONITOR	INVESTIGATE	SENT TO DSM	
CREST General C	ondition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		V	,					
Settlement		V						
Erosion Rills		V						
Animal Burrows		N						
Misalignment		V						ļ
Vegetation (greater than 12")		V						-
UPSTREAM EMBANKMENT General C	ondition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Animal Burrows		V		0.6%				
Erosion Rills		V			U U			
Slope Protection / Rip Rap		N	34					-
Vegetation (greater than 12")		V						-
DOWNSTREAM EMBANKMENT General C	ondition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		V						
Sloughing / Bulging		/						
Seepage		V						
Sink Holes		V						ļ
Sand Boils (indicate if flowing and color)		1		1/				ļ
Animal Burrows	V		FINDIN	3/ PILLING		V		
Erosion Rills		V		V	- 10-10 - 1-10 -			
Vegetation (greater than 12")		1		W. Colonia				ļ
	Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)		V			A.			
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		1			v			