CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid		Date:	5 31 23
Impoundment Name:	Ash Pond		· Time:	11:49 410
IEPA Number:	W0218140002-01	1	Inspector(s):	D. Huber
Sky: CLEAR Temp.:	87°E	Precip. (last 48 hrs):	0.00	Pool Elev.: -18"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sheets as nécessary. Circle Gene	, in contactor					-	ACTION		
ITEM		NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO	
CREST Gener	ral Condition.	Good Fa	ir / Poor	Repairs:	Date:	7-4-22 MT 5254			
Cracking		TI.						ļ	
Settlement		V.		AND THE RESIDENCE OF THE PARTY				-	
Erosion Rills		V						-	
Animal Burrows		N						-	
Misalignment		V							
Vegetation (greater than 12")		-		1				-	
UPSTREAM EMBANKMENT General	ral Condition:	Good/Fa	ir / Poor	Repairs:	Date:				
Cracking		V						-	
Sloughing / Bulging		V					-		
Seepage		V					-	+	
Sink Holes						_	_	-	
Animal Burrows		/		a A a			-	-	
Erosion Rills		V		8			-	-	
Slope Protection / Rip Rap		N	(4					+	
Vegetation (greater than 12").									
DOWNSTREAM EMBANKMENT Gene	ral Condition	Good Fa	ir / Poor	Repairs:	Date:				
Cracking		V					-	-	
Sloughing / Bulging		V					-	-	
Seepage		1					-		
Sink Holes		1					-	+	
Sand Boils (indicate if flowing and color)		V		163		-	1-	+-	
Animal Burrows			5 ino ing	y / FILLING		V	-	\vdash	
Erosion Rills		/					-	-	
Vegetation (greater than 12")		V					-	-	
SPILLWAY(S) Gene	ral Condition:	Good / Fa	nir / Poor	Repairs:	Date:	_	+	+	
Actively Flowing (provide depth)		V		and the same of th			-		
Obstructions Present		V				_	-	+	
Seepage		V					-	+	
Sand Boils (indicate if flowing and color)		1					-	-	
Erosion Rills		V		(#)	* 1				