CCR Impoundment Weekly Inspection 35 III. ADM. Code 845 / 40 CFR Part 257

		33 166.	ADIVI. COUR 0-15 / TR		1.11/22
	Station:	Kincaid		Date:	06/19/65
	Impoundment Name:	Ash Pond		Time:	12:10 119
8	IEPA Number:	W0218140002-01		Inspector(s):). Hubus
Sky:	CLEAR Temp.:	79°F	Precip. (last 48 hrs):	0.00"	Pool Elev.: - 22.0

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEN		NO	DESCRIPTION		ACTION		
					MONITOR	INVESTIGATE	SENT TO DSM
CREST General Con	dition:	Good	Fair / Poor Repairs:	Date:			
Cracking		7	,	19.			
Settlement		V					-
Erosion Rills		V			_		
Animal Burrows		V	•				-
Misalignment		V	***				-
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT General Con	dition	Good	Fair / Poor Repairs:	Date:			_
Cracking		P					<u> </u>
Sloughing / Bulging		V					-
Seepage		V				_	-
Sink Holes		V			_		-
Animal Burrows		V,	υ e _{-ti}				-
Erosion Rills		V			_	<u> </u>	-
Slope Protection / Rip Rap		V	11)			-	-
Vegetation (greater than 12")		V					
DOWNSTREAM EMBANKMENT General Cor	dition:	Good	Fair / Poor Repairs:	Date:		ļ	-
Cracking		V					ļ
Sloughing / Bulging		V			_		ļ
Seepage		V					
Sink Holes		V				-	-
Sand Boils (indicate if flowing and color)		V	1/		1	-	-
Animal Burrows	V		Finding / FILLIN	7	-	-	-
Erosion Rills		V				-	-
Vegetation (greater than 12")	100	V			_		
	dition:	Good	/ Fair / Poor Repairs:	Date:		_	+
Actively Flowing (provide depth)		V	1,000				-
Obstructions Present		N				-	-
Seepage		V			_	-	-
Sand Boils (indicate if flowing and color)		V					-
Erosion Rills		V	ĸ	•			