## CCR Impoundment Weekly Inspection

	35 ILL.	ADM. Code 845 / 40 (		1-1-2
Station:	Kincaid		Date:	06/21/23
Impoundment Name:	Ash Pond		Time:	10103 AM
IEPA Number:	W0218140002-0	1	Inspector(s):	D. Husen
Sky: CLEAR Temp.:	82°F	Precip. (last 48 hrs):	0-00"	Pool Elev.: - 22 "
VEC " raspansas raquira description (	size denth, extents, co	olor) and location in "DESCR	IPTION" section. "NO" res	sponse indicates no issues were observed

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO			1		CHO	N
			DESCRIPTION			MONITOR	INVESTIGATE	SENT TO DSM
CREST General Con	dition:	Good	Fair / Poor Re	pairs:	Date:			
Cracking	1	V	3		11			
Settlement		V						
Erosion Rills		V		3514 BOTTIS 1101				
Animal Burrows		V						
Misalignment		N		Water				-
Vegetation (greater than 12")		1						-
UPSTREAM EMBANKMENT   General Con	dition	Good	/ Fair / Poor R	epairs:	Date:			-
Cracking		V						-
Sloughing / Bulging		1						-
Seepage		V						-
Sink Holes		V.						-
Animal Burrows		N		· (				-
Erosion Rills		V						-
Slope Protection / Rip Rap		N	T)					├
Vegetation (greater than 12")		V						-
DOWNSTREAM EMBANKMENT General Con	dition:	Goog	/ Fair / Poor R	epairs:	Date:			<u> </u>
Cracking		V					-	
Sloughing / Bulging		1						-
Seepage		N						-
Sink Holes		N					<u> </u>	<u> </u>
Sand Boils (indicate if flowing and color)		1					-	-
Animal Burrows	V						-	-
Erosion Rills		V						-
Vegetation (greater than 12")	(€3	V		The state of the s	A SHIP STATE OF THE STATE OF TH		-	
	dition:	Good	/ Fair / Poor R	epairs:	Date:		-	-
Actively Flowing (provide depth)		V						
Obstructions Present		V		- Walter			-	-
Seepage		V						+-
Sand Boils (indicate if flowing and color)		IV						-
Erosion Rills		V	κ		(#)			