CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	35	ILL. A	DM. Code 845 / 40	D CFR Part 25 7	1 2 1	~ ^		
Station:	Kincaid			Da	te: 07/20/3	<u> </u>		
Impoundment Name:	Ash Pond	Table of Table 1	3	· Tin	ne: 12:00 I	PM		
IEPA Number:	W021814000	2-01	a	Inspector	s): D. Hub	UK		
Sky: CLSY Temp.:	18°F		recip. (last 48 hrs):	0.00 h	Pool	Elev.:	- {	3"
'YES" responses require description (at the time of inspection. If "ACTION additional sheets as nécessary. Circle	" selected is "INVE	STIGAT	TE", please indicate dat	CRIPTION" section. "NO' e forwarded via email to	' response Indicates no Dam Safety Manager (Issues v DSM) .	vere ob Attach	served
additional sheets as necessary. Circle deficition					P	CTION		
ITEM	YE	s NO		DESCRIPTION	, and the second	MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condition	Good	/ Fair / Poor	Repairs:	Date:		-	
Cracking	No.	1				,		
Settlement		V					-	
Erosion Rills	-	V			-	2 Marian Marian		. <u> </u>
Animal Burrows		V		A MA TO				
Misalignment		V	, 1997) (A Commission of the		NAMES OF THE PROPERTY OF THE P			
Vegetation (greater than 12")		V			OUR DONNERS OF THE PROPERTY OF			
UPSTREAM EMBANKMENT		Goog	/ Fair / Poor	Repairs:	Dațe:			
Cracking		V						
Sloughing / Bulging	The state of the s	V	A Company of the Comp					
Seepage		V	m) 30 M M M M M M M M M M M M M M M M M M	ALVA III.	and the same of th	<u> </u>		
Sink Holes		V				<u> </u>		<u> </u>
Animal Burrows		V		. ,	Market Company			
Erosion Rills		V			-			
Slope Protection / Rip Rap		V				ļ		
Vegetation (greater than 12")		V			The state of the s			
DOWNSTREAM EMBANKMENT		1: (Good	Fair / Poor	Repairs:	Date:			
Cracking		7					<u> </u>	
Sloughing / Bulging		7	A CONTRACTOR OF THE PROPERTY O		AND THE PROPERTY OF THE PROPER		<u></u>	
Seepage		1	The state of the s				ļ	
Sink Holes		1		ac southwest South and the sou			<u> </u>	
Sand Boils (indicate if flowing and color)		1					<u> </u>	ļ
Animal Burrows			FINDING	/ Killing		√		<u> </u>
Erosion Rills		V	/					
Vegetation (greater than 12")		V	,					
SPILLWAY(S)	General Condition	n/Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide de		1						
Obstructions Present		V	AND STREET, MANUFACTURE AND STREET, COMMENT OF STREET, COMMENTAL STREET, COMMENTS OF S	Appliful to the second sec	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAM			
Seepage		1	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE	Marine and the property of the second				
Sand Boils (indicate if flowing and color)		V.	,					
Janu Dons (marcare it nowing and color)		//		The state of the s		1	1	1

Erosion Rills