CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

a .	35 ILL.	ADM. Code 845 / 40	CFR Part 257	101/22
Station:	Kincaid		Date:	10/04/05
Impoundment Name:	Ash Pond		Time:	9:00 AM
IEPA Number:	W0218140002-01		Inspector(s):	D. Hubar
Sky: CLUAR Temp.:	75°F	Precip. (last 48 hrs):	0.00	Pool Elev.: - 15.0

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sneets as necessary. Circle General Co		NO	DESCRIPTION			1	ACTION		
ITEM						MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Cor	dition:	Good	/ Fair / Poor	Repairs:	Date:		Zain in .		
Cracking		V	All Marketines					-	
Settlement		V	AND THE PROPERTY OF THE PROPER	- Constitution of the Cons	and the second s			<u> </u>	
Erosion Rills		W	ZAMBONIO ZIZIZIA DA ZAZIZIA ZIZIZIZIA ZAZIZIA ZIZIZIZIA ZIZIZIZI	The state of the s	The state of the s			-	
Animal Burrows		V	AND DESCRIPTION OF THE PROPERTY OF THE PROPERT				ALTERNATION COLUMN	-	
Misalignment		V			THE RESERVE OF THE PROPERTY OF		-		
Vegetation (greater than 12")		1		and the second s			-	-	
UPSTREAM EMBANKMENT General Condition		Good	/ Fair / Poor	Repairs:	Date:		1 115.000		
Cracking		V						 	
Sloughing / Bulging		V	The state of the s				ļ		
Seepage		V			OHEST AND THE SECOND OF THE SE	\dashv	<u> </u>	-	
Sink Holes		V					<u> </u>	-	
Animal Burrows		N		1. 3.	AND THE CONTRACTOR OF THE CONT		ļ		
Erosion Rills		1					├		
Slope Protection / Rip Rap		~					-	-	
Vegetation (greater than 12")	V			Maria de Caractería de Car				-	
DOWNSTREAM EMBANKMENT General Con	ndition	Good	/ Fair / Poor	Repairs:	Date:		-		
Cracking		V		Wallet Or William Control of Cont			<u> </u>		
Sloughing / Bulging		V			THE CONTROL OF THE PARTY OF THE			-	
Seepage		V		THE PARTY OF THE P			-	-	
Sink Holes		V			100-04-04-04-04-04-04-04-04-04-04-04-04-0			-	
Sand Boils (indicate if flowing and color)		V		COMMENT OF THE PARTY OF THE PAR	All the All Property and the A		_	-	
Animal Burrows	V						-	-	
Erosion Rills		V	WARRANGE CONTROL OF THE PARTY O	MATERIAL PROPERTY OF THE PROPE					
Vegetation (greater than 12")	V		A THE CONTRACT OF THE PARTY OF	The state of the s					
SPILLWAY(S) General Co	ndition	Good	/ Fair / Poor	Repairs:	Date:			-	
Actively Flowing (provide depth)		V		THE CONTROL OF A CANADA STATE OF THE STATE O					
Obstructions Present		V					-	-	
Seepage		V					-	-	
Sand Boils (indicate if flowing and color)		V		A CONTRACTOR OF THE CONTRACT O	and a guidant construction of the second constru		-	_	
Erosion Rills		IV			A W S		1		