## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid		Date:	0/18/23
Impoundment Name:	Ash Pond		Time:	1:45 17
IEPA Number:	W0218140002-01		Inspector(s):	). Husen
Sky: Clousy Temp.:	69°F	Precip. (last 48 hrs):	0.00	Pool Elev.: -15"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sheets as necessary. Chere elements			CONTRACTOR			1-	ACTION		
ITEM		NO	DESCRIPTION			MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Co	ondition:	Good	Fair / Poor	Repairs:	Date:				
Cracking		V			THE RESERVE THE THE PROPERTY OF THE PROPERTY O		ļ	<u> </u>	
Settlement		V	WARRANGE TO THE RESIDENCE OF THE PROPERTY OF T	Market and the second s				-	
Erosion Rills		V	DATE TO SERVICE THE SERVICE TH	Addition to the second	AND THE PROPERTY OF THE PROPER			-	
Animal Burrows		1	AND THE RESERVE OF THE PARTY OF		CONTRACTOR DE LA CONTRA			-	
Misalignment		V	THE RESIDENCE OF THE PARTY OF T	MARIE SALVERS OF THE	CONTRACTOR OF THE PROPERTY OF				
Vegetation (greater than 12")		X				_	-	-	
UPSTREAM EMBANKMENT General Co	ondition:	Good	Fair / Poor	Repairs:	Date:			-	
Cracking		V		with the state of	AND THE PARTY OF T	_		-	
Sloughing / Bulging		V	The second state of the se		CHEMICAL STREET, THE CONTROL STREET, CONTROL OF STR			-	
Seepage		V	AND THE RESIDENCE OF THE PARTY		NOTES CONTRACTOR OF THE PROPERTY OF THE PROPER		-	┼	
Sink Holes		V					-	+	
Animal Burrows		V		1	The second secon		-	-	
Erosion Rills		V					-	-	
Slope Protection / Rip Rap		V					-	-	
Vegetation (greater than 12")	1	K	Mowing			V			
DOWNSTREAM EMBANKMENT General C	ondition	Good	/ Fair / Poor	Repairs:	Date:			-	
Cracking		V				-	<u> </u>	-	
Sloughing / Bulging		V						-	
Seepage		V					-		
Sink Holes		V		aki inama kin'a a manana kao amin'ny fivondronana ao amin'ny faritr'i Amerika.	A STATE OF THE STA		┼	+-	
Sand Boils (indicate if flowing and color)		1	1	En ina			-	-	
Animal Burrows		1	FINSINS/	TYLLING		V	+-	-	
Erosion Rills		\v/	MANUFACTURE OF THE PROPERTY OF		ONE WATER TO SHEET WHEN THE PROPERTY OF THE PR		<b> </b>		
Vegetation (greater than 12")		1	Monry			V	-		
SPILLWAY(S) General C	Condition	: 6000	l/ Fair / Poor	Repairs:	Date:		-	-	
Actively Flowing (provide depth)		V				STATE OF THE PERSON NAMED IN COLUMN 1	_		
Obstructions Present		V					-	-	
Seepage		V			Manufacture of the state of the		<del> </del>		
Sand Boils (indicate if flowing and color)		12,			Legione and the second		-	_	
Erosion Rills		V	*		V				