CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

•	35 ILL. A	DM. Code 845 / 40 CFR Part 257	101/10
Station:	Kincaid	4	COLUMN TO THE PROPERTY OF THE
Impoundment Name:	Ash Pond	· · · · · · · · · · · · · · · · · · ·	Time: 1:30 P/9
IEPA Number:	W0218140002-01		ector(s): 1). 1-1454
sky: CLEAR Temp.:	12°F	recip, (iast 46 iiis).	Pool Elev.: -17"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sheets as nécessary. Circle General Con	uition	101 68	CIT SECUOII.		(C.C	ACTION		
, item	YES	NO		DESCRIPTION	,	MONITOR	INVESTIGATE	SENT TO DSW
CREST General Conc	iition:	Good	Fair / Poor Re	pairs:	Date:	1.07.		
Cracking		-		and the second s	www.akivi@YUTBI			
Settlement		/	THE PARTY OF THE P	and the state of the latest control of the state of the s			2	
Erosion Rills		V	Annual property and the second se					
Animal Burrows		1		ang pangalika di kacamang pangan kalip di kacamang pangan ka	tall and the growth and the control of the second of the s		anto o sumana	
Misalignment		V	Market Market (Construction of the Construction of the Constructio		A Share where we are supplied to the supplied of the supplied			AND THE PERSON NAMED IN
Vegetation (greater than 12")		1						
UPSTREAM EMBANKMENT General Con-	dition:		/Fair/Poor Re	epairs:	Date:			
Cracking		V	white Makes can are greated with an analysis and the particular and th	The state of the s				
Sloughing / Bulging	may white the months of the	V	·	onther there were the second of the second o				
Seepage		V	, , , , , , , , , , , , , , , , , , , ,					<u> </u>
Sink Holes	ļ.,,,,	V	With a second of the second of					
Animal Burrows		/		1				
Erosion Rills		V				ļ		<u> </u>
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")		V	Williams and the second	neumonomi historia (m. 12 mallos in 147 mm. 12 manus (m. 147)			/	
DOWNSTREAM EMBANKMENT General Con	dition:	Good	/ Fair / Poor Re	epairs:	Date:			·
Cracking	_	1/			Anna di manana mana			
Sloughing / Bulging		1			A Company of the Comp			
Seepage				· · · · · · · · · · · · · · · · · · ·	- Maria Institution of the Control o		<u> </u>	
Sink Holes		V				<u> </u>	<u> </u>	
Sand Boils (indicate if flowing and color)		1				1		-
Animal Burrows		W	FINSING !!	- China		<i>V</i>		<u> </u>
Erosion Rills		V	THE RESERVE THE PROPERTY OF TH	endine rapo menut rikleri k irabanca menekk mesem	and the state of t			
Vegetation (greater than 12")	<u> </u>	1		William Company of the Company of th	SACRIM CONTRACTOR STATE OF THE SECTION OF THE SECTI			
SPILLWAY(S) General Con	dition:	Coop	/ Fair / Poor R	epairs:	Date:			
Actively Flowing (provide depth)		7	COMMONORMY MAINTENANCE OF THE PARTY AND THE SECOND PROPERTY OF THE PARTY OF THE PAR	and the second constitution of the second consti		_		
Obstructions Present		1					 	
Seepage		1			y community to the second of 	<u> </u>	<u> </u>	
Sand Boils (Indicate If flowing and color)		V		- dayle fill the same and the s				
Erosion Rills		1/	,		· · · · · · · · · · · · · · · · · · ·		<u> </u>	